



Security Bulletin for Xona Clientless Secure Gateway (CSG)

Bulletin ID	Date Published	Severity
XONA19-06	April 30, 2019	High

Summary

The power button required no inference of intent when shutting down the system via the power button. The front panel features a sleek button with a shallow throw and requires light pressure to activate. The design could lead to accidental operation.

Affected Products

Product	Version	Hardware
Xona Clientless Secure Gateway	3.2 and earlier	ML-350

Solution

A security update for this issue is available in the 3.2.3 release update file. To receive this update, login to your support portal account on the *xonasystems.com* website or contact us for assistance by email: support@xonasystems.com.