



Security Bulletin for Xona Clientless Secure Gateway (CSG)

Bulletin ID	Date Published	Severity
XONA19-10	April 30, 2019	High

Summary

The TPM failed to initialize during boot.

Affected Products

Product	Version	Hardware
Xona Clientless Secure Gateway	3.2 and earlier	ML-350

Solution

A security update for this issue is available in the 3.2.3 release update file. To receive this update, login to your support portal account on the *xonasystems.com* website or contact us for assistance by email:

support@xonasystems.com.