



Security Bulletin for Xona Clientless Secure Gateway (CSG)

Bulletin ID	Date Published	Severity
XONA19-01	April 30, 2019	Critical

Summary

When starting the Xona CSG Setup Terminal, the system would not capture any SIGINT sent via the keyboard interface immediately after authenticating from the command line.

Affected Products

Product	Version	Hardware
Xona Clientless Secure Gateway	3.2 and earlier	ML-350

Solution

A security update for this issue is available in the 3.2.3 release update file. To receive this update, login to your support portal account on the *xonasystems.com* website or contact us for assistance by email: support@xonasystems.com.